

RTSI Reliability Testing Services, Inc.

P.O. Box 365 Genoa, AR 71840

Ph. (870) 653-6838

Specializing in Predictive Testing

Location: Brine Tank


Equipment: Brine Tank--SE Side at drain valve

Problem: N/A

Observation: Sludge is built up to approximately 3' around the circumference of the tank. The "dips" in the sludge level are where the drain valves are located.

Rise: N/A

THERMOGRAPHIC REPORT



49300004.IRI					
ITEM	TYPE	AVG TEMP	MAX TEMP	MIN TEMP	EMISS
Whole Image	Image	94.15	119.14	72.89	0.92
S1	Spot	96.67	97.55	95.76	0.92
S2	Spot	83.64	84.41	83.04	0.92

**Repair
Comments:**

